

BELZONA STOPS THE LEAK ON FIREWATER SYSTEM

ID: 5430



PROBLEM

The piping was old and had not been taken care of. Many clamps on the lines, but leaks were starting to appear under the clamps. There were other places in the line where actual holes had appeared from corrosion.

APPLICATION SITUATION

Firewater piping at a tank terminal.

APPLICATION METHOD

Application was carried out in accordance with a modified Belzona Know-How System Leaflet VPF-11.

BELZONA FACTS

Customer is very satisfied with the fact that the pipe will not corrode any more due to the fact a polymer steel now encapsulates the piping. Belzona was picked as other wraps had been tried and failed and the clamps were not sufficient to adequately stop the leaks.

INDUSTRY

Marine

LOCATION

Tank Terminal, South Louisiana, USA

APPLICATION DATE

September 2014

PRODUCTS

Belzona 1121 (Super XL Metal)

Belzona 9341 (Reinforcement Sheet)

SUBSTRATE

Carbon steel

PHOTOS

1. One of the holes in the pipe
2. Water flowing from the pipe
3. Area of the pipe that was leaking
4. Application completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

