


BELZONA REPAIRS A DOCK HOSE BEFORE INSPECTION

ID: 5431



PROBLEM

Over the years as the dock hose had been drug around the deck and over shipside, the hose had been cut and gouged.

APPLICATION SITUATION

Rubber Dock Hose with cuts.

APPLICATION METHOD

After proper surface preparation, the application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SOS-12.

BELZONA FACTS

Customer spent less than \$50.00 to repair cosmetic cut in hose for Coast Guard approval to keep using the hose versus spending \$2,500 or more for a new hose.

INDUSTRY

Marine

LOCATION

Terminal Dock, Louisiana, USA

APPLICATION DATE

July 2013

PRODUCTS

Belzona 2311 (SR Elastomer)
Belzona 2911 (Conditioner)

SUBSTRATE

Rubber

PHOTOS

1. Area being prepared for repair.
2. Area after Belzona 2911 applied.
3. Belzona 2311 applied.
4. Finished repair before tape removed.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

