

BELZONA PROVIDES A NEW SEAMLESS FLOOR AT A SCHOOL

ID: 5438



PROBLEM

After twenty years the laminate flooring suffered from age and had become unsanitary. Odor and visible delamination of the laminate was a concern.

APPLICATION SITUATION

School bathroom and classroom floors.

APPLICATION METHOD

After proper surface preparation, the application was carried out in accordance with Belzona Know-How System Leaflets FPA-3 and FPA-8.

BELZONA FACTS

Belzona provided the client with the solution to eliminate safety and health challenges. The adhesion near the seams was failing and delamination increased tears and created holes, so the removal of the contaminated linoleum flooring was of the essence. After adequate preparation of the concrete, Belzona 5231 was applied in two coats, freshening up and creating a safe and healthy area. The application of Belzona 5231 took place after 6pm and was ready for foot traffic by the next morning.

INDUSTRY

Buildings & Structures

LOCATION

School, Edmonds, WA, USA

APPLICATION DATE

2014

PRODUCTS

Belzona 5231 (SG Laminate)

SUBSTRATE

Concrete

PHOTOS

1. Laminate failing in several areas
2. Showing signs of use
3. Seams suspect to hygiene standards
4. Happy customer in a healthy & safe environment

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

