



BELZONA REBUILDS AND PROTECTS RUDDERS

ID: 5442



PROBLEM

Vessel rudders are subjected to continuous erosion and cavitation attack.

APPLICATION SITUATION

Rudder

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SOS-1/2

BELZONA FACTS

INDUSTRY

Marine

LOCATION

BC, Canada

APPLICATION DATE

December 2004

PRODUCTS

Belzona 1311 (Ceramic R Metal) Belzona 1341 (Supermetalglide)

SUBSTRATE

Mild steel

PHOTOS

1. Rudders in set up after blasting ready for application. 2. Rudders after application of 2 coats of Belzona 1341 Supermetalglide. 3. Condition of rudders / rudder horn after 2½ years of service with Belzona coating.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

