

BELZONA REBUILDS BOW THRUSTER

ID: 5446



PROBLEM

The fiberglass surround designed to eliminate bimetallic corrosion around the bow thruster insert was not able to protect the area from cavitation attack.

APPLICATION SITUATION

Bow thruster

APPLICATION METHOD

Application carried out in accordance with Belzona Know-How System Leaflet SOS-1/2

BELZONA FACTS

The use of Belzona allowed localized repairs to be executed with a minimal amount of down time.

INDUSTRY

Marine

LOCATION

BC, Canada

APPLICATION DATE

1999

PRODUCTS

Belzona 1111 (Super Metal) Belzona 1341 (Supermetalgilde)

SUBSTRATE

Aluminum and stainless steel

PHOTOS

1. Fairing in the damaged areas. 2. Fairing in the damaged areas. 3. Entire bow thruster protected with 2 coats of Belzona 1341 Supermetalgilde.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.