


# BELZONA REPAIRS SHIPS GENERATOR SHAFT

ID: 546



## PROBLEM

Worn generator drive shaft located in a narrow, confined place.

## APPLICATION SITUATION

Generator drive shaft of a transport ship.

## APPLICATION METHOD

Application was carried out in accordance with Belzona® Know-How System Leaflet MPT-2.

## BELZONA FACTS

Belzona successfully repaired the shaft in a cramped environment without disassembling the shaft. This allowed the ship to keep schedule without delay.

## INDUSTRY

Marine

## LOCATION

Shipping company - Egypt

## APPLICATION DATE

February 2005

## PRODUCTS

Belzona 1111 (Super Metal)

## SUBSTRATE

Steel

## PHOTOS

1. View of the generator shaft prior to the repair.
2. Surface preparation in progress.
3. Form was applied. Then excess material was removed.
4. Completed shaft repair.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

