

# BELZONA REPAIRS AND PROTECTS BULB GENERATOR SET

ID: 5472



## PROBLEM

Important infiltration and corrosion between stainless steel jacket and turbine housing.

## APPLICATION SITUATION

Bulb generator set.

## APPLICATION METHOD

The damaged junction was repaired with Belzona 1111 and protected with Belzona 1341. The application was completed by the customer.

## BELZONA FACTS

Quick, on-site and cold repair.

## INDUSTRY

Power

## LOCATION

Hydropower Plant - France

## APPLICATION DATE

March 2001

## PRODUCTS

Belzona 1111 (Super Metal)

Belzona 1341 (Supermetalgilde)

## SUBSTRATE

Steel and Stainless steel

## PHOTOS

1. General view of the housing
2. Junction between steel and stainless steel
3. Completed repair and protection

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

