




BELZONA PROTECTS BUFFER STONE WITH INTERNAL COATING

ID: 5474



PROBLEM

The pressurized equipment was subject to abrasion and regularly cleaned with high pressure. The temperature of the hydrocarbons was up to 150°C.

APPLICATION SITUATION

Buffer store with a diameter of 3m and length of 11m, transporting crude oil.

APPLICATION METHOD

The application was carried out during a shutdown of the refinery. The entire application was completed in a one coat system.

BELZONA FACTS

The application was completed in only 2 days. Belzona 1591 was specified by the inspection service of the refinery.

INDUSTRY

Oil & Gas

LOCATION

Refinery, France

APPLICATION DATE

October 2013

PRODUCTS

Belzona 1591 (Ceramic XHT)

SUBSTRATE

Steel

PHOTOS

1. Application on grit-blasted substrate
2. Completing the application on the top part of the tank
3. Inspecting the thickness of the coating

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

