

# BELZONA MAKES FOR BETTER SHOPPING

ID: 5477



## PROBLEM

Concrete floor has broken out near a relief cut. With heavy forklift traffic during overnight stocking causing the damage, it is unsafe for pedestrian traffic during business hours. Previous patch material has been used but it breaks out soon after application, causing even more damage to the concrete.

## APPLICATION SITUATION

Damaged concrete at a wholesale shopping store.

## APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet FPA-5 using 1" strips of a Belzona mixing board as the former to maintain the relief cut.

## BELZONA FACTS

Existing patch materials needed to be reapplied a couple of times per year. When the existing patch material was removed, it came loose in large pieces, thus showing it had not bonded to the concrete substrate and still had a very strong chemical odor even after being applied months before. Upon opening and mixing Belzona 4111 for the repair, the customer remarked that there was no odor coming from the Belzona product. This customer is happy that they have a long-lasting solution that is easy for them to use. They will save money of repeat maintenance to the same damage.

## INDUSTRY

Buildings & Structures

## LOCATION

Spokane, WA, USA

## APPLICATION DATE

September 2014

## PRODUCTS

Belzona 4111 (Magma-Quartz)

## SUBSTRATE

Concrete

## PHOTOS

1. Prior damage and patch. Patch removed.
2. Starting the application using the mixing board formers.
3. Finishing the application with the formers. After removing the formers.
4. One month later. Still looking brand new.

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

[www.belzona.com](http://www.belzona.com)

