

BELZONA PROTECTS CONDENSER TUBE SHEET

ID: 548



PROBLEM

Corrosion of the tube sheets of two condensers.

APPLICATION SITUATION

Steam unit condensers at a large power station.

APPLICATION METHOD

Application was carried out in accordance with Belzona know-How system leaflet HEX-3.

BELZONA FACTS

Belzona provided long term protection, increasing the life of the tube sheet, decreasing other repairing and maintenance costs.

INDUSTRY

Power

LOCATION

Power plant, Egypt

APPLICATION DATE

January 2004

PRODUCTS

Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Steel

PHOTOS

1. General view of the Condenser
2. The corroded tube sheet
3. Applying Belzona 1321 to the tube sheet
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.