


BELZONA SAVES SIGNIFICANT DOWNTIME FOR CEMENT PLANT

ID: 550



PROBLEM

Bearing area of the 155mm shaft was down due to bearing failure, causing the entire operation to shut down.

APPLICATION SITUATION

Crusher shaft

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-1 and MPT-2.

BELZONA FACTS

An alternative method would be to weld and grind the shaft, but this is not possible in situ. Removal of the shaft from the equipment would require over 100 hours of downtime as no spare part was available. With Belzona, this customer was back up and running in hours, not days, saving significant amounts of money from lost production and downtime.

INDUSTRY

Cement

LOCATION

Cement plant - United Arab Emirates

APPLICATION DATE

May 2005

PRODUCTS

Belzona 1121 (Super XL-Metal)

SUBSTRATE

Steel

PHOTOS

1. Surface preparation in progress
2. Prepared surface, ready for Belzona to be applied
3. Completed application
4. General view of crusher shaft in operation after the application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

