

BELZONA FORMS 24" FLAT FACE FLANGE

ID: 5517



PROBLEM

Existing coating had failed leading to corrosion of the vessel internals and severe loss of metal on the adjacent flanges. This 24 inch flange was for the Perspex sight port.

APPLICATION SITUATION

Deck water seal of inert gas generator system on an FPSO. Seal handles sea water at ambient temperatures.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-13. An aluminium former was fabricated. This was accurately positioned using shims to allow accurate reconstruction of the flange face with Belzona 1111 to be completed.

BELZONA FACTS

Client was unable to use hot work and had restricted time. Application was carried out over a weekend and the entire solution, from first notification, including former fabrication, was completed in less than a week. A number of other flanges were reformed using the Belzona reusable formers. The vessel was returned to service with minimum disruption to the production cycle.

INDUSTRY

Oil & Gas

LOCATION

Oil Major, North Sea, UK

APPLICATION DATE

November 2014

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Carbon steel

PHOTOS

1. The damaged flange face. Note damage to internal lining 2. Aluminium former in place 3. Former removed showing reformed flange face with Belzona 1111 4. flange re-assembled with Perspex window in place

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

