


BELZONA REPAIRS RUBBER PONTON

ID: 553



PROBLEM

The rubber pontoon was worn out in several areas from the effects of water and impact.

APPLICATION SITUATION

Rubber pontoon in a water ride.

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

BELZONA FACTS

These rubber pontoons are pushed through the lake by strong flow. It was critical and unsafe to use the pontoons in there condition. Belzona 2121 was used to repair the worn out areas and also to protect the pontoon from future damage, saving the cost of new units.

INDUSTRY

General Industry

LOCATION

Amusement park - Egypt

APPLICATION DATE

December 2004

PRODUCTS

Belzona 2121 (D&A Hi-Coat Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. General view of the rubber pontoons
2. The worn out pontoons
3. Surface preparation
4. Applying Belzona 2121 to the damaged areas

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.