


BELZONA UPGRADES SAFETY OF STAIRS AT MULTI-STORY CAR PARK

ID: 5558



PROBLEM

Steps presented a slip hazard to users of the car park.

APPLICATION SITUATION

Worn steps.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-8. Belzona 9221 was encapsulated in Belzona 4411 and applied in an even coat.

BELZONA FACTS

These stairs have been used by thousands of people over the last 7 years and they were shutting down these stairs every couple of months to re-paint prior to the Belzona 4411 application.

INDUSTRY

LOCATION

Local Council, UK

APPLICATION DATE

April 2008

PRODUCTS

Belzona 4411 (Granogrip)

Belzona 9221 (Surefoot Aggregate White)

SUBSTRATE

Concrete

PHOTOS

1. Original painted grip system
2. Belzona 4411 grip system applied in 2008
3. Application revisited in 2015

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

