

BELZONA REPAIRS A LARGE HYDRAULIC RAM

ID: 558



PROBLEM

Deep and wide scores in many areas of the ram.

APPLICATION SITUATION

Eight meter hydraulic ram of a transport winch

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

BELZONA FACTS

There were scores in many areas of the ram causing many leakages and fluid losses. Belzona saved the replacement costs of the ram, returning it successfully to service.

INDUSTRY

Oil & Gas

LOCATION

Offshore oil company - Egypt

APPLICATION DATE

May 2005

PRODUCTS

Belzona 1121 (Super XL-Metal)

SUBSTRATE

Chromed steel

PHOTOS

1. General view of the hydraulic ram
2. Scores on the ram
3. The ram after repair
4. Finishing the surface then cleaning it

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

