


BELZONA REPAIRS OFFLOADING HOSE ABOVE WATER

ID: 5585



PROBLEM

During the normal operation of transfer, staff noticed a small tear in the rubber hose. Three weeks later, the tear had tripled in size and this is when the crew called the experts.

APPLICATION SITUATION

Damaged offloading hose

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SOS-12. The surface was roughened before the application of Belzona 2911 followed by the reinforced system of Belzona 2211 to the damaged areas.

BELZONA FACTS

The application was completed in just 4 hours and for a fraction of the cost of replacement. Belzona provided a long-term solution in just a few hours.

INDUSTRY

Oil & Gas

LOCATION

FPSO, Santos, Brazil

APPLICATION DATE

April 2015

PRODUCTS

Belzona 2911 (Elastomer QD Conditioner)
Belzona 2211 (MP Hi-Build Elastomer)
Belzona 9341 (Reinforcement Tape)

SUBSTRATE

Rubber

PHOTOS

1. View of damaged hose
2. Surface preparation
3. Completed application
4. Overview of the application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

