

BELZONA KEEPS WATER OUT AND THE ENVIRONMENT SAFE

ID: 5586



PROBLEM

The crew noticed a tear in the rubber of the off loading hose and took the quick decision to call in the experts to repair it with Belzona.

APPLICATION SITUATION

Off loading hose damage.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SOS-12. The surface was roughened before the application of Belzona 2911, followed by the reinforced system of Belzona 2211 to the damaged areas.

BELZONA FACTS

The quick decision to make the repair with Belzona prevented the seawater to continue into the inside of the hose, which could lead to the disruption of the hose and oil leak. The repair was made in just four hours.

INDUSTRY

Oil & Gas

LOCATION

FPSO, Brazil

APPLICATION DATE

April 2015

PRODUCTS

Belzona 2911 (Elastomer QD Conditioner)
Belzona 2211 (MP Hi-Build Elastomer)
Belzona 9341 (Reinforcement Tape)

SUBSTRATE

Rubber

PHOTOS

1. Damaged area
2. Belzona 2911
3. Reinforcement sheet
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

