

BELZONA REPAIRS PVC PUMP

ID: 559



PROBLEM

Cracked casing

APPLICATION SITUATION

PVC dosing pumps (2)

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System leaflet CEP-6. The cracks were stabilized by drilling and widening it then filled with Belzona® 1111.

BELZONA FACTS

PVC cracks are critical problems, welding cannot be used here. Belzona stops the cracks in a short time saving the high costs of new units.

INDUSTRY

General Industry

LOCATION

Construction company - Egypt

APPLICATION DATE

September 2003

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

PVC

PHOTOS

1. The crack in the PVC pump
2. Stabilising the crack
3. Cracks after preparation
4. Cracks repaired

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

