


# BELZONA SEALS OIL AND GAS LEAK IN A TRANSFORMER

ID: 5598



## PROBLEM

The bushing was leaking oil and gas, creating an environmental hazard and affecting the proper operation of the transformer.

## APPLICATION SITUATION

Transformer bushing

## APPLICATION METHOD

The application was carried out in accordance with a modified version of Belzona Know-How System Leaflet VPF-11. The area was properly prepared and sealed with Belzona 2111 and coated with Belzona 2121.

## BELZONA FACTS

Belzona solutions offered great benefits to the client who avoided the high cost to replace the part while preventing further contamination to the environment.

## INDUSTRY

Power

## LOCATION

Electricity Substation, USA

## APPLICATION DATE

1997

## PRODUCTS

Belzona 2111 (D & A Hi-Build Elastomer)  
Belzona 2121 (D & A Hi-Coat Elastomer)

## SUBSTRATE

Steel

## PHOTOS

1. Substation overview
2. Application under progress
3. Sealed area
4. Completed application

For more examples of Belzona Know-How in Action, please visit [khia.belzona.com](http://khia.belzona.com)

Belzona products are manufactured  
under an ISO 9001 Registered  
Quality Management System.

[www.belzona.com](http://www.belzona.com)

