

BELZONA REPAIRS AND PROTECTS TURBINE ROTOR

ID: 5615



PROBLEM

Wear caused by the effects of erosion and cavitation to the rotor with a waterfall height of 110 meters.

APPLICATION SITUATION

Turbine rotor.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet CEP-1. The surface was prepared according to the standard NACE 2 (equivalent to SA 2 ½) with dry abrasive blast to near white metal. Belzona 1311 was applied to smooth the wear on the vanes (holes and loss of thickness) and then, Belzona 2141 was partially applied in certain areas of the rotor. Subsequently, Belzona 2141 was applied in 2 coats.

BELZONA FACTS

Belzona attended to the customer's expectation, recovering and protecting the surface of the rotor with a long-lasting solution.

INDUSTRY

Power

LOCATION

Hydroelectric Power Plant, Brazil

APPLICATION DATE

September 2011

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 2141 (ARC-Fluid Elastomer)
Belzona 2941 (Elastomer SP-Conditioner)

SUBSTRATE

Stainless steel

PHOTOS

1. Worn area of the rotor
2. Defining the application area
3. Application under progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

