

BELZONA REPAIRS RUBBER PRESS ROLL

ID: 5636



PROBLEM

Rubber press roll had a hole caused by a tool impact, which made the roll unusable and not being able to create a smooth gasket.

APPLICATION SITUATION

Rubber press roll used to laminate gasket sheets together.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-9. The surface preparation and the application was carried out with the use of hand tools.

BELZONA FACTS

The cost of the Belzona materials used for the application was less than \$100. Replacement of the roll would have cost the asset owners thousands of dollars.

INDUSTRY

Pulp & Paper

LOCATION

Northeastern USA

APPLICATION DATE

June 2015

PRODUCTS

Belzona 2311 (SR Elastomer)

Belzona 2911 (Elastomer QD Conditioner)

SUBSTRATE

Rubber & steel

PHOTOS

1. Rubber press roll
2. Deep hole in press roll
3. Cleaned, prepped and masked off hole to be repaired
4. Repaired hole and used a razor blade to cut and smooth final surface

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

