

NO JOB IS TOO SMALL FOR BELZONA

ID: 565



PROBLEM

Activities during a motocross race caused a stripped thread. Piece of equipment quite expensive.

APPLICATION SITUATION

Yamaha YZ 250 cc - 2001

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet ENC-2. The area was post-cured at 50° C for five hours to ensure that the oil seals were not damaged.

BELZONA FACTS

Still in service after months of intensive use.

INDUSTRY

Transport

LOCATION

Motocross enthusiast - Northern Italy (Piacenza)

APPLICATION DATE

January 2005

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Aluminium casting

PHOTOS

1. Yamaha YZ 250
2. Broken thread
3. Completed work
4. See the rebuilt fillet

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA