

BELZONA TANK BASE SEALING SYSTEM OFFERS COST-EFFECTIVE SOLUTION

ID: 5650



PROBLEM

The original tank base seal cracked allowing moisture penetration to tank base. This led to corrosion under the tank base.

APPLICATION SITUATION

Storage tank at tank farm.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

BELZONA FACTS

The Belzona system met the clients' urgent requirement for a system to resist water, weather and fire. The cost effective Belzona system has been specified into the client's global standard and all the 40 tanks at the farm are to be protected in 2 years.

INDUSTRY

Chemical & Petrochemical

LOCATION

International Petroleum Company, China

APPLICATION DATE

October 2014

PRODUCTS

Belzona 3211 (Lagseal)

SUBSTRATE

Carbon steel and concrete

PHOTOS

1. Overview of the tank farm
2. Damaged tank base
3. Applying Belzona 3211
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

