


BELZONA PROTECTS A STERN TUBE (NON-BEARING AREAS) ON A A US NAVY SHIP

ID: 5664



PROBLEM

The U.S. Navy required superior protection against erosion and corrosion in the non-bearing area of the stern tube when the ship was dry docked.

APPLICATION SITUATION

Stern Tube on a U.S. Navy Ship

APPLICATION METHOD

Areas in stern tube were spot repaired with Belzona 1111 and then coated with a brush.

BELZONA FACTS

Belzona lasts through the expected time between 5 year Stern Tube inspections by the American Bureau of Shipping (ABS).

INDUSTRY

Marine

LOCATION

Portland, OR, USA

APPLICATION DATE

May 2015

PRODUCTS

Belzona 1111 (Super Metal)

Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

1. Stern Tube Preparation
2. Stern Tube Coating
3. Completed Stern Tube Coating

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

