

BELZONA SMOOTHS AIRPORT RUNWAY

ID: 5685



PROBLEM

Prior patching material failed. A steel plate was used to cover the hole.

APPLICATION SITUATION

Airport runway

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA. Old and loose material was removed. Then, a mixture of gravel and Belzona 4111 was used to bulk up the patch. A batch of pure Belzona 4111 was used to finish the job.

BELZONA FACTS

The material was applied at 11:00 PM and the runway was open by 8:00 AM.

INDUSTRY

General Industry

LOCATION

Airport, Northern Texas, USA

APPLICATION DATE

2014

PRODUCTS

Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Old patch failed and removed
2. Hole prepared for application
3. Bulk material to fill the hole
4. Finished with pure Belzona 4111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

