

BELZONA TAKES THE SLIP OUT OF THE FLOOR

ID: 5686



PROBLEM

The VCT square tiles were coming up with the water dripping on them from the ice machine, causing a sanitary and slipping problem.

APPLICATION SITUATION

Tile was coming loose and holding water, causing mold and a slip problem in hotel.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA. The tile was removed and the floor was levelled with Belzona 4131. A coat of Belzona 5811 was applied over the whole area and a coat with aggregate was applied in front of the ice machine.

BELZONA FACTS

The floor was recently fixed and lasted only a few months. Belzona provided a permanent solution for the customer.

INDUSTRY

Buildings & Structures

LOCATION

Building and Structures, Northern Texas, USA

APPLICATION DATE

2014

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 5811 (Immersion Grade)

SUBSTRATE

Concrete

PHOTOS

1. Tile removed
2. Floor levelled with Belzona 4131
3. Coated floor prepared for nonskid
4. Completed floor application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

