


BELZONA STOPS THE LEAKS ON HVAC TUBES

ID: 57



PROBLEM

Leaking coolant

APPLICATION SITUATION

Tube in HVAC coil

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How Leaflet VPF-11a.

BELZONA FACTS

After six years the repair is still in place.

INDUSTRY

Chemical & Petrochemical

LOCATION

Petrochemical Plant in Texas, U.S.A.

APPLICATION DATE

1991

PRODUCTS

Belzona1111 (Super Metal)

SUBSTRATE

Copper

PHOTOS

1. An area was cut to gain access to the leaking pipe
2. Leak stopped with Belzona 1111 (Super Metal)

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

