

LIVE WATER LEAK CLAMPED WITH BELZONA

ID: 5704



PROBLEM

The hot water line was leaking from an expansion tank to the 2" line. The supply of hot water could not be shut off since it fed water to the emergency room.

APPLICATION SITUATION

Hot water line at a hospital

APPLICATION METHOD

A clamp was fabricated at a machine shop. The clamp had a threaded drain and matched threaded fittings. Belzona 1111 was applied to secure clamp to the hot water line.

BELZONA FACTS

This saved a major disruption to the hospital's emergency room. There was no alternative solution except replacement.

INDUSTRY

General Industry

LOCATION

Hospital, Northern Texas, USA

APPLICATION DATE

2011

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Steel Pipe

PHOTOS

1. Leaking pipe cleaned
2. Clamp ready to go
3. Application of Belzona 1111
4. Clamp installed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

