

PINTLE HOUSING REPAIR WITH BELZONA

ID: 573



PROBLEM

Pintle housing had become oversized due to corrosion.

APPLICATION SITUATION

Pintle housing

APPLICATION METHOD

Application was carried out in accordance with Belzona® Know-How System Leaflet SOS-3.

BELZONA FACTS

Belzona was used to allow an in-situ repair with minimum repair downtime. The other option of welding and machining would be difficult to accomplish, potentially dangerous due to heat distortion, and significantly more expensive.

INDUSTRY

Marine

LOCATION

Cement transportation ship, Egypt

APPLICATION DATE

July 2004

PRODUCTS

Belzona 1121 (Super XL-Metal)

SUBSTRATE

Steel

PHOTOS

1. General view of the ship
2. The oversized pintle housing
3. After applying Belzona Release Agent to the pintle, Belzona 1121 was applied to the pintle
4. Pintle housing was perfectly repaired

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

