

BELZONA GIVES NEW LIFE TO GROCERY STORE FLOOR

ID: 5772



PROBLEM

Receiving floor at a grocery store was so rough that groceries were falling off the pallets.

APPLICATION SITUATION

Damaged floor

APPLICATION METHOD

The floor was ground and conditioned with Belzona 4911 to prepare the surface for application. Then, 1/4 of Belzona 4111 was applied to level the floor.

BELZONA FACTS

The application was started in the evening and ready for service by the first delivery. A previous product had failed within months.

INDUSTRY

Buildings & Structures

LOCATION

Grocery Store, Northern Texas, USA

APPLICATION DATE

2014

PRODUCTS

Belzona 4111 (Magma-Quartz)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Preparation completed and conditioned with Belzona 4911
2. Mixing station
3. Application in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

