

LEAKING VENT SEALED WITH BELZONA

ID: 5773



PROBLEM

A roof vent was installed, but ponding water leaked through the black mastic roof sealer.

APPLICATION SITUATION

Leaking vent

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1. The surface was prepared by scraping away the gravel. Then, Belzona 3121 was applied with fabric to seal the duct.

BELZONA FACTS

The roof was leaking in the production area from the vent. It was sealed the day before it rained, saving a production shutdown.

INDUSTRY

Buildings & Structures

LOCATION

Buildings and Structures, Northern Texas, USA

APPLICATION DATE

2013

PRODUCTS

Belzona 3121 (MR7)

SUBSTRATE

Tar and gravel roof

PHOTOS

1. Newly installed vent
2. Prepared area
3. Fabric being applied
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

