

SPALLED STEPS NO LONGER A SAFETY HAZARD WITH BELZONA REPAIR

ID: 5814



PROBLEM

The stairs had spalled due to environmental freeze and thaw effect.

APPLICATION SITUATION

Stairs to a memorial recreation center.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-10 for fixing or securing anchor bolts or hand rails. The surface was prepared using a grinder and the surface was brushed to remove any loose concrete. Belzona 4911 was applied to the area using a stiff bristle brush. Belzona 4131 was applied directly onto the conditioned surface in accordance with Belzona Instructions For Use.

BELZONA FACTS

Belzona 4131 has outstanding environmental protection, is impermeable to water and provides long term protection. Belzona 4131 is easily applied using a trowel, thus, no specialist tools are required.

INDUSTRY

Buildings & Structures

LOCATION

Waterloo, ON, Canada

APPLICATION DATE

September 2014

PRODUCTS

Belzona 4131 (Magma-Screed)

Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete

PHOTOS

1. Prior to application
2. Completed application
3. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

