


HOLDING PANS IN CHILLER UNITS NO LONGER CORRODING WITH BELZONA REPAIR

ID: 5817



PROBLEM

The holding pans in both of the chiller units had corroded and were leaking onto the roof.

APPLICATION SITUATION

Holding pans in chiller units.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-15 for sealing and protecting containment areas. The unit was prepared using a grit blaster to remove all scale and corrosion. Belzona 1111 was applied to repair the holes and seal all the edges. Belzona 5811 was applied to the holding pans in accordance with Belzona Instructions For Use.

BELZONA FACTS

Belzona 5811 is a brush or spray applied coating which provides outstanding protection from the effects of salt water, acid, alkalis, alcohol, hydrocarbon and the environment. The Belzona solution was cost effective and was completed in one day.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

Waterloo, ON, Canada

APPLICATION DATE

May 2015

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 5811 (Immersion Grade)

SUBSTRATE

Steel

PHOTOS

1. View of the holding pans
2. Application in progress
3. Application in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

