

BELZONA REPAIRS HOLE ON SCUM TANK

ID: 5827



PROBLEM

Hole caused by corrosion.

APPLICATION SITUATION

Scum tank at a water pollution control plant.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet HEX-9 for repairing leaking pipework. The surface was prepared using a grinder to roughen the surface and Belzona 9111 was used to clean the area. Belzona 1161 was applied around the hole and then a piece of metal was placed over the product. Once the piece of metal is in place, Belzona 1161 was applied around the pipe in accordance with Belzona Instructions For Use.

BELZONA FACTS

Belzona 1161 bonds firmly to oily, wet and not fully prepared substrates. This system is simple to use and does not require specialist tools. By using Belzona 1161, the customer eliminated expensive replacement costs and minimized downtime.

INDUSTRY

Water / Wastewater

LOCATION

Toronto, ON, Canada

APPLICATION DATE

November 2014

PRODUCTS

Belzona 1161 (Super UW-Metal)
Belzona 9111 (Cleaner Degreaser)

SUBSTRATE

Steel

PHOTOS

1. Prior to application
2. Preparation in progress
3. Application in progress
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

