

BELZONA PREVENTS CORROSION DAMAGE TO 18' RISER

ID: 5840



PROBLEM

Corrosion damage to riser.

APPLICATION SITUATION

18' riser on an offshore platform.

APPLICATION METHOD

The surface was blasted to the requirements of SSPC SP10 (Near White Metal). Profile measurements were checked and the surface was cleaned and degreased with Belzona 9111. Belzona 1121 was then applied to 18' of the riser to fill pitting in order to restore the original pipe thickness. Belzona 1121 was sanded to abrade the surface and wiped down with Belzona 9111. Belzona 1982 was applied in 5 layers. Belzona 9382 was wrapped over the Superwrap II application area to consolidate and compress during cure.

BELZONA FACTS

The repair and application of Belzona SuperWrap II was completed in less than 8 hours, in addition to the 24 hours required for the system to cure. Belzona had quality control throughout the application and all hold points surveyed were registered.

INDUSTRY

Oil & Gas

LOCATION

Texas, USA

APPLICATION DATE

August 2015

PRODUCTS

Belzona 1121 (Super XL-Metal)
Belzona 1982 (SuperWrap II)
Belzona 9111 (Cleaner Degreaser)
Belzona 9381 (Reinforcement Sheet)
Belzona 9382 (Release Film)

SUBSTRATE

Carbon Steel

PHOTOS

1. View of 18' riser prior to repair
2. Surface preparation
3. Application of Belzona 1982 complete
4. View of repair with Belzona 9382 wrapped over SuperWrap II during cure

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

