


COURTHOUSE PLAZA STAIRS REPAIRED WITH BELZONA

ID: 5849



PROBLEM

Concrete loss and creation of trip hazards.

APPLICATION SITUATION

Main entryway plaza steps from the street and into the courthouse had several unsightly spalls and cracks in the concrete caused by winter freeze thaw and use of chemical deicers.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-5. The surface was prepared by hand cleaning with power tools.

BELZONA FACTS

One bucket of Belzona 4111 and an afternoon of labor saved the courthouse the inconvenience of closing the stairs for 3 - 5 days that would have been required by the traditional mortar repairs. Additionally, it was a lot less expensive utilizing in house labor.

INDUSTRY

Buildings & Structures

LOCATION

County Courthouse, Vermont, USA

APPLICATION DATE

2006

PRODUCTS

Belzona 4111 (Magma-Quartz)
Belzona 4911 (Magma TX Conditioner)

SUBSTRATE

Concrete Stairs

PHOTOS

1. View of damaged step
2. Other visible damages to steps
3. Completed repair
4. Overview of completed repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

