


BELZONA PROVIDES GREAT RETURN ON INVESTMENT

ID: 587



PROBLEM

Worn shaft caused air handler to not operate effectively.

APPLICATION SITUATION

Air handler shaft

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

BELZONA FACTS

A new shaft would have cost \$2,700. For only \$200 worth of Belzona, the shaft was repaired in place and returned to service quickly. Literally tens of thousands of shafts have been repaired with Belzona providing our customers with a great return on investment.

INDUSTRY

General Industry

LOCATION

Building Maintenance Company, South Texas USA

APPLICATION DATE

July 2005

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 9411 (Release Agent)

SUBSTRATE

Steel

PHOTOS

1. Worn area of air handler shaft
2. Surface preparation in-situ
3. Cured Belzona 1111
4. Air handler back in service

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.


BELZONA®