

BELZONA REPAIR TO KING PIN BUSH HOUSING

ID: 588



PROBLEM

Wear of the seats leading to increased clearance

APPLICATION SITUATION

Front end loader king pin connection

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-8.

BELZONA FACTS

Belzona returned the equipment to service in one day. The Belzona repair was simple to carry out and saved machining.

INDUSTRY

General Industry

LOCATION

Metal processing plant, Bulgaria

APPLICATION DATE

July, 2003

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast iron

PHOTOS

1. View of the damaged connection.
2. Belzona 1111 applied on the prepared housing surface.
3. The pin coated with release agent was used to form the housing.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.