


BELZONA SEALS VALLEY GUTTERS

ID: 5887



PROBLEM

Full replacements of the gutter would have caused excessive disruption to the working areas below.

APPLICATION SITUATION

Several valley gutters constructed from cast steel had begun to leak from the joints. These leaks were causing damage to the stored materials below.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-6.

BELZONA FACTS

Belzona 3131, a liquid applied membrane, allowed the applicators to coat the existing substrate without removing large sections of the roof. The Belzona 3131 system is flexible, which has allowed a long lasting repair over the problem joints where competitor materials had failed.

INDUSTRY

General Industry

LOCATION

Manufacturing Plant, Scotland

APPLICATION DATE

October 2014

PRODUCTS

Belzona 3131 (WG Membrane)

SUBSTRATE

Cast iron

PHOTOS

1. Length of gutters before surface preparation
2. Section of gutter showing build up of dirt & corrosion
3. Length of gutter coated
4. Standing water still an issue but the gutter is now leak free

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

