

TIRE REPAIR WITH BELZONA ELASTOMER

ID: 589



PROBLEM

A piece of metal penetrated the sidewall.

APPLICATION SITUATION

Rear tire of front end loader.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet SHM-1.

BELZONA FACTS

The client insisted on repairing this tire based on his good experience with Belzona solutions and the alternative expensive replacement. The tire was in service nearly one year following the repair.

INDUSTRY

General Industry

LOCATION

Processing plant, Bulgaria

APPLICATION DATE

December 2003

PRODUCTS

Belzona 2211 (MP Hi-Build Elastomer)

SUBSTRATE

Rubber

PHOTOS

1. Size of the tire clearly evident
2. The metal alongside and the damage it caused
3. Prepared and conditioned area
4. Finished Elastomer repair

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

