

SHAFT JOURNAL OF STONE CRUSHER REPAIRED WITH BELZONA

ID: 590



PROBLEM

Shaft damaged by seized bearing.

APPLICATION SITUATION

Main shaft of primary stone crusher

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-2.

BELZONA FACTS

Belzona allowed vital equipment to be returned to service with minimum disruption to production.

INDUSTRY

Chemical & Petrochemical

LOCATION

Chemical industry, Bulgaria

APPLICATION DATE

July 2002

PRODUCTS

Belzona 1321 (Ceramic S-Metal)
Belzona 9411 (Release Agent)

SUBSTRATE

Steel

PHOTOS

1. Preparing shaft surface
2. Forming with manufactured pipe clamp
3. View of repair with former removed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

