


CONCRETE STEP REPAIR WITH BELZONA

ID: 5912



PROBLEM

Concrete steps were broken and deteriorating.

APPLICATION SITUATION

Concrete steps leading up to the entrance of building.

APPLICATION METHOD

The old concrete was removed so that Belzona 4111 could fill in the spots. After the steps were smoothed over, Belzona 4411 was added with some aggregate.

BELZONA FACTS

This entranceway was an eyesore and a trip hazard. The use of Belzona products provided a solution to both issues in a cost effective manner. This area is used frequently for special events, such as private catering and weddings.

INDUSTRY

Buildings & Structures

LOCATION

Building & Structures, North Carolina, USA

APPLICATION DATE

August 2015

PRODUCTS

Belzona 4411 (Granogrip)
Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Prior to application
2. Preparing the surface by removing busted concrete
3. Application of Belzona 4411 with some aggregate
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

