


BEARING HOUSING REPAIR WITH BELZONA

ID: 593



PROBLEM

Housing damage after bearing seized leading to increased clearance.

APPLICATION SITUATION

Centrifugal pump bearing housing

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet MPT-6.

BELZONA FACTS

Belzona solution saved both time and replacement cost allowing the equipment to be quickly returned to operation.

INDUSTRY

Water / Wastewater

LOCATION

Watersupply company, Bulgaria

APPLICATION DATE

April, 2003

PRODUCTS

Belzona 1111 (Super Metal)

SUBSTRATE

Cast iron

PHOTOS

1. Preparing surface
2. Belzona 1111 applied
3. Housing with restored dimensions after machining

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

