

BELZONA REPAIRS AND PROTECTS CORRODED EXHIBITION SUPPORTS

ID: 5936



PROBLEM

During the life of the exhibition, the metal support structure underneath the exhibition was heavily corroded by the oxidising nature of the Bromine Water. The museum were concerned about the corrosion and thus the decreasing strength of the supports.

APPLICATION SITUATION

A museum located in Bristol city centre had an exhibit which uses 5% Brominated Water.

APPLICATION METHOD

Application was carried out in accordance with Belzona System Leaflet TCC-5. The corroded metal structure was blasted back to bare metal using sponge blasting as the client was concerned about the dust created by using regular grit blasting. Areas that were especially corroded and damaged were rebuilt using Belzona 1111. Belzona 5811 was applied with a top coat of Belzona 5111 to protect against oxidation and provide a good colour match.

BELZONA FACTS

The Belzona application was considerably cheaper and easier than a complete replacement of the support structure. It provided a quick turnaround time that will provide long term corrosion protection.

INDUSTRY

Commercial Facilities

LOCATION

Museum, Bristol, UK

APPLICATION DATE

September, 2015

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 5811 (Immersion Grade)
Belzona 5111 (Ceramic Cladding)

SUBSTRATE

Steel

PHOTOS

1. Supports before application
2. Supports before application
3. Application of 5811 underway
4. Finished application showing close colour match achieved with Belzona 5111

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

