

BELZONA SAVES WASTEWATER PLANT SIGNIFICANT REPLACEMENT COST

ID: 594



PROBLEM

Worn edges caused propeller to be in-efficient. Client was going to replace with new equipment.

APPLICATION SITUATION

Client was about to replace the diffuser propeller when Belzona came to the rescue.

APPLICATION METHOD

Application was carried out in accordance with a modified version of Belzona Know-How System Leaflet CEP-1.

BELZONA FACTS

For only \$200 worth of Belzona, the customer was able to save the \$2500 replacement cost!

INDUSTRY

Water / Wastewater

LOCATION

Wastewater Utility in South Texas, USA

APPLICATION DATE

June 2005

PRODUCTS

Belzona 1311 (Ceramic R-Metal)
Belzona 1321 (Ceramic S-Metal)

SUBSTRATE

Brass

PHOTOS

1. Propeller blasted
2. Belzona 1311 and 1321 being applied
3. First coat of Belzona 1321 complete
4. Completed application

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

