

LIVE LEAKS STOPPED AND SEALED WITH BELZONA

ID: 5982



PROBLEM

The tanks suffered from severe corrosion up to through-wall defects with some live seawater leakage. It was only possible to stop the filtration plant for two hours.

APPLICATION SITUATION

Vertical sea water tanks in the activated carbon filtration plant of a coastal Hydrocarbon storage tank farm.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-1. Surface preparation was carried out using an MBX bristle blaster. Several metal plates were cold bonded with Belzona 1212 to cover thin wall and through wall defects.

BELZONA FACTS

For a traditional weld repair, the customer would have to shut down the system and completely empty the tanks. Due to its surface-tolerant and fast-curing properties, Belzona 1212 was applied directly onto leaking tanks, bypassing the need for a shutdown. In a couple of hours the customer forgot about his problem.

INDUSTRY

Chemical & Petrochemical

LOCATION

Tank Farm, Genova, Italy

APPLICATION DATE

December 2015

PRODUCTS

Belzona 1212

SUBSTRATE

Carbon Steel

PHOTOS

1. General view of equipment
2. Detailed leakage
3. Plate bonded with Belzona 1212
4. Close up of one of the bonded plates

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com


BELZONA

Copyright © 1952-2026 Belzona International Limited.