

BELZONA REPAIRS DAMAGED FLOOR IN A WAREHOUSE

ID: 5987



PROBLEM

Forklifts carrying palettes with bags of cement, as well as customers' trucks that come into the warehouse for loading, suffered damages to wheels and tires when passing over damaged area.

APPLICATION SITUATION

Concrete floor of a warehouse in a cement plant was damaged due to heavy traffic of forklifts and trucks, as well as storage of palettes with cement over time. The damage was situated on joint areas of large concrete plates (3m x 5m) of the floor.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1 and FPA-6.

BELZONA FACTS

Because of continuous 24/7 production, the warehouse must be in use all the time and only small portion of it could be out of use. According to customer, Belzona offered the best value for money, allowing the customer's staff to do repairs themselves in periods with less activity in the warehouse. Site revisited after 1 year shows that repaired area is still in perfect shape.

INDUSTRY

General Industry

LOCATION

Cement plant in Croatia

APPLICATION DATE

February 2014

PRODUCTS

Belzona 4911 (TX Conditioner)

Belzona 4111 (Magma Quartz)

Belzona 4521 (Magmaflex Fluid)

SUBSTRATE

Concrete

PHOTOS

1. View of application area
2. Application in progress
3. Application in progress
4. Situation after 8 years in service.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

