

BELZONA "SMOOTH RIDE" APPLICATION OF EXPANSION JOINTS SAVES BOTTLES

ID: 5998



PROBLEM

The warehouse floor suffered from uneven surfaces and bumps, causing product spills and long man hours to ensure cleanliness and safety.

APPLICATION SITUATION

Concrete floor at a warehouse.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

BELZONA FACTS

The relationship between the suppliers, customers and the warehouse started to go down the hill due to frequent delays in shipping out the products. Interruptions in loading due to the need to clean up spillage and breakage caused delays in the shipping of product. This simple repair from a complete kit of Belzona 4111 went very easily and all the products needed were in the kit. This repair made for smooth travel on the forklifts and stopped the product waste, saving both money and good customer relations.

INDUSTRY

Buildings & Structures

LOCATION

Montana, USA

APPLICATION DATE

2003

PRODUCTS

Belzona 4911 (Magma TX Conditioner)
Belzona 4111 (Magma-Quartz)

SUBSTRATE

Concrete

PHOTOS

1. Concrete below grade at old doorway.
2. Applying Belzona 4911 after surface preparation.
3. Belzona 4111 trowelled smoothly over the defect areas.
4. Repair holding up to forklift traffic years later.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com



Copyright © 1952-2026 Belzona International Limited.