

O-RING FIT RESTORED WITH BELZONA

ID: 6



PROBLEM

Eroded O-Ring fit.

APPLICATION SITUATION

Air compressor cooler waterbox.

APPLICATION METHOD

The application was carried out in accordance with Belzona Know-How Leaflet FBC-5.

BELZONA FACTS

Belzona saved costly downtime and restored the operation of the compressor. After several years, the restoration is still holding.

INDUSTRY

Power

LOCATION

Power Plant in North Texas

APPLICATION DATE

1996

PRODUCTS

Belzona 1111 (Super Metal)
Belzona 1121 (Super XL-Metal)
Belzona 1341 (Supermetalglide)
Belzona 9411 (Release Agent)

SUBSTRATE

Cast Iron

PHOTOS

1. Corrosion and eroded o-ring fit.
2. A new O-Ring was used to form the fit.
3. Entire waterbox was coated.
4. O-Ring fit restored and back online.

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured
under an ISO 9001 Registered
Quality Management System.

www.belzona.com

