

BELZONA CHILLER PROTECTION

ID: 600



PROBLEM

Corrosion of the tube sheet and water box.

APPLICATION SITUATION

Chiller unit from the hotel air conditioning plant

APPLICATION METHOD

Application was carried out in accordance with Belzona Know-How System Leaflet HEX-3.

BELZONA FACTS

Long term protection was provided with minimum down time. The preparation and application arrangements did not disrupt the hotels operation as required by the management.

INDUSTRY

Heating, Ventilation & Air Conditioning

LOCATION

Five star hotel in Egypt

APPLICATION DATE

April 2005

PRODUCTS

Belzona 1341 (Supermetalgilde)

SUBSTRATE

Steel

PHOTOS

1. The corroded water box
2. Surface preparation
3. Tube sheet completed
4. Water box completed

For more examples of Belzona Know-How in Action, please visit khia.belzona.com

Belzona products are manufactured under an ISO 9001 Registered Quality Management System.

www.belzona.com

Copyright © 1952-2026 Belzona International Limited.

